

## March '99 Occurrence List

MO/YR	CLS	TITLE	OR NO.	PO	CATEGORY	REPORT TYPE	DT 1	DT 2
03/01/1999	0	AVIATION FUEL TRUCK MODIFICATION CAUSES NEAR MISS IN IGNITING TRUCK ENGINE STARTING FLUID DUE TO HEAT FROM EXHAUST PIPE	NVOO-BNLV-RSLO-1999-0001	DP	OFF-NORMAL	NOTIFICATION	03/24/1999	
<b>Total for Class</b>		1						
03/01/1999	2	DIESEL DRIVEN FIREWATER PUMP BATTERY ACID EXPLOSION AT CFA-1603	ID-LITC-CFA-1999-0003	EM	OFF-NORMAL	NOTIFICATION	03/11/1999	
03/01/1999	2	EMPLOYEE SLIPPING ON ICE MELT RESIDUE INSIDE AN OFFICE HALLWAY HOSPITALIZED WITH FINGER FRACTURE AND SURGERY	ALO-KC-AS-KCP-1999-0004	DP	OFF-NORMAL	FINAL	03/10/1999	03/11/1999
03/01/1999	2	DURING WASTE VERIFICATION, PRESSURIZED DRUM LID RELEASED - FROM DRUM CONTAINING CARBON BLOCKS FOR FLUORINE GENERATION	ORO-BJC-PORTENVRES-1999-0004	WM	OFF-NORMAL	NOTIFICATION	03/05/1999	

—

MO/YR	CLS	TITLE	OR NO.	PO	CATEGORY	REPORT TYPE	DT 1	DT 2
03/01/1999	2	INADEQUATE AUTHORIZATION BASIS REQUIRED CONFIGURATION CONTROLS - POTENTIAL EXISTS FOR INADVERTENT MIXING OF 40% FERROUS SULFAMATE (FS) AND 64% NITRIC ACID (U)	SR-WSRC-FCAN-1999-0008	EM	UNUSUAL	NOTIFICATION	03/22/1999	
<b>Total for Class</b>		4						
03/01/1999	3	AIRBORNE LEAD EXPOSURE TO SUBCONTRACTOR PAINTER OF 795.3 MICROGRAMS/CU. METER FOR 430 MINUTES VERSUS 500 MICROGRAMS/CU. METER OSHA PEL	OAK-LBL-OPERATIONS-1999-0001	SC	OFF-NORMAL	NOTIFICATION	03/24/1999	
03/01/1999	3	ON 3/18/99, OXYGEN ANALYZER HIGH OXYGEN ALARM - ROOM 154, GLOVEBOX 502	RFO-KHLL-SOLIDWST-1999-0008	EM	OFF-NORMAL	NOTIFICATION	03/22/1999	
03/01/1999	3	ON 3/5/99, SAFETY EXCLUSION GATE ACCESS PROCEDURE VIOLATION AT TA-16 HIGH EXPLOSIVES AREA	ALO-LA-LANL-HEMACHPRES-1999-000	DP	OFF-NORMAL	NOTIFICATION	03/12/1999	
03/01/1999	3	ON 3/4/99, SMOLDERING CHEMICAL IN DUMPSTER DISCOVERED - NON- HAZARDOUS WASTE TO SANITARY LANDFILL	SR-WSRC-LTA-1999-0010	EM	OFF-NORMAL	NOTIFICATION	03/04/1999	

—

MO/YR	CLS	TITLE	OR NO.	PO	CATEGORY	REPORT TYPE	DT 1	DT 2
03/01/1999	3	2/10/99 HYDROGEN CHLORIDE GAS RELEASE FROM "EMPTY" CONTAINER DURING CHECKING FOR SALVAGE AND DISPOSAL OF CONTAINER	HQ-GOPE-FETC-1999-0002	FE	OFF-NORMAL	NOTIFICATION	03/11/1999	
03/01/1999	3	ON 3/26/99, POTENTIAL UNREVIEWED SAFETY QUESTION (USQ) WAS NOTED - MINIMUM FIRE SYSTEM PRESSURE LIMIT CHANGE FOR BUILDING 9204- 2E	ORO-LMES-Y12NUCLEAR-1999-0027	DP	OFF-NORMAL	NOTIFICATION	03/26/1999	
03/01/1999	3	ON 3/24/99, OXYGEN DEFICIENCY OF 18.4% VERSUS MINIMUM STANDARD OF 19.5% DISCOVERED AT 329 BUILDING MANUAL LIQUID NITROGEN DEWAR STATION	RL-PNNL-PNNLBOPER-1999-0006	SC	OFF-NORMAL	NOTIFICATION	03/25/1999	
03/01/1999	3	ON 3/16/99, SEVERAL GLOVEBOX OVERHEAT DETECTORS FOR GLOVEBOX 59 FAILED QUARTERLY SURVEILLANCE	RFO-KHLL-371OPS-1999-0016	EM	OFF-NORMAL	NOTIFICATION	03/17/1999	
03/01/1999	3	241-S-102 SALTWELL PUMP MAY HAVE BEEN OPERATED WHILE THE 241-S STANDARD HYDROGEN MONITORING SYSTEM (SHMS) WAS NOT IN OPERATIONAL MODE	RL-PHMC-TANKFARM-1999-0018	EM	OFF-NORMAL	NOTIFICATION	03/22/1999	

—

MO/YR	CLS	TITLE	OR NO.	PO	CATEGORY	REPORT TYPE	DT 1	DT 2
03/01/1999	3	ON 3/1/99, GAS ANALYSIS RESULTS WERE INCOMPLETE PRIOR TO GAS GENERATION TESTING OF A 55 GALLON DRUM - FLAMMABLE CONSTITUENTS EXCEEDED 500 PPM LIMIT	RFO-KHLL-371OPS-1999-0013	EM	OFF-NORMAL	UPDATE	03/02/1999	03/12/1999
03/01/1999	3	PROPANE CYLINDER LEAK AT K-1415 STORAGE SHED	ORO-BJC-K25GENLAN-1999-0005	EM	UNUSUAL	NOTIFICATION	03/15/1999	
03/01/1999	3	FAILURE TO COMPLY WITH A WESF ADMINISTRATIVE CONTROL - NON-FIRE SYSTEM VALVES ON WATER/CHEMICAL SUPPLY LINES TO HOT CELLS CLOSED BUT NOT LOCKED FOR HYDROGEN PREVENTION	RL-PHMC-WESF-1999-0006	EM	OFF-NORMAL	NOTIFICATION	03/03/1999	
03/01/1999	3	POTENTIAL DISCOVERY ISSUE OF SEALED BOTTLES OF PLUTONIUM BEARING OIL MAY HAVE EXCEEDED HSP 31.11 SAFE STORAGE TIME FOR HYDROGEN CONCENTRATION (U)	RFO-KHLL-SITEWIDE-1999-0004	EM	OFF-NORMAL	NOTIFICATION	03/08/1999	
03/01/1999	3	TRANSPORTATION OF 15.4 HAZARDOUS MATERIAL ON 3/17/99 WITHOUT PROPER DOCUMENTATION (U)	SR-WSRC-HCAN-1999-0017	EM	OFF-NORMAL	NOTIFICATION	03/18/1999	

—



MO/YR	CLS	TITLE	OR NO.	PO	CATEGORY	REPORT TYPE	DT 1	DT 2
03/01/1999	3	ON 2/26/99, IMPROPER MOVEMENT OCCURRED OF 1.4S EXPLOSIVES FROM BUILDING 12-79 TO FIRING SITE 11	ALO-AO-MHSM-PANTEX-1999-0017	DP	OFF-NORMAL	NOTIFICATION	03/01/1999	
03/01/1999	3	ON 2/25/99, TANK 13 HYDROGEN MONITOR OUT OF CALIBRATION ROLL-UP REPORT (U)	SR-WSRC-HTANK-1999-0006	EM	OFF-NORMAL	UPDATE	03/01/1999	03/25/1999
03/01/1999	3	ON 3/5/99, POTENTIAL UNREVIEWED SAFETY QUESTION (USQ) ASSOCIATED WITH AUTHORIZATION BASIS (AB) FOR 9215 COMPLEX - "LESS FLAMMABLE" HYDRAULIC FLUID NOT DESIGNATED IN FIRE HAZARDS ANALYSIS	ORO-LMES-Y12NUCLEAR-1999-0022	DP	OFF-NORMAL	NOTIFICATION	03/08/1999	
03/01/1999	3	ON 3/1/99, INADVERTENT ADDITION OF PROCESS WATER TO CELLS OCCURRED (U)	SR-WSRC-LTA-1999-0009	EM	OFF-NORMAL	NOTIFICATION	03/02/1999	
03/01/1999	3	ON 3/5/99, TANK 49 ISOKINETIC SAMPLER OUT OF SERVICE - HOT WIRE FLOW ELEMENT FAILED (U)	SR-WSRC-ITP-1999-0012	EM	OFF-NORMAL	UPDATE/FINAL	03/08/1999	03/30/1999

—

MO/YR	CLS	TITLE	OR NO.	PO	CATEGORY	REPORT TYPE	DT 1	DT 2
03/01/1999	3	ON 2/21/99, A STOP WORK ORDER FOR SAFETY CONCERNS - LACK OF ABILITY TO LIFT AND SET A SHEET PILE - RANDOM MOTIONS- WAS ISSUED TO A SUBCONTRACTOR OF DYN McDERMOTT PERTROLEUM OPERATIONS CO. (DM)	HQ-SPR-WH-1999-0003	FE	OFF-NORMAL	UPDATE	03/05/1999	03/08/1999
<b>Total for Class</b>		20						
03/01/1999	4	ON 3/11/99, SURVEILLANCE PROCEDURE WAS FOUND NOT TO IDENTIFY ALL ROOMS SUBJECT TO INSPECTION FOR COMBUSTIBLE LOADING	ALO-LA-LANL-CMR-1999-0006	DP	OFF-NORMAL	UPDATE/FINAL	03/11/1999	
03/01/1999	4	ON 3/4/99, LOW LEVEL MIXED WASTE - PONDCRETE WASTE CRATE TARE WEIGHT CALCULATION ERRORS - RADIOACTIVITY LEVELS RECORDED WAS HIGHER THAN ACTUAL SHIPMENT LEVELS	RFO-KHLL-WSTMGTOPS-1999-0003	EM	OFF-NORMAL	NOTIFICATION	03/04/1999	
03/01/1999	4	ON 3/11/99, ONE YEAR STORAGE TIME LIMIT WAS DISCOVERED EXCEEDED FOR ONE DRUM OF NON-RADIOACTIVE PCBS - BEGIN DATE 10/31/97	ORO-BJC-K25WASTMAN-1999-0005	EM	OFF-NORMAL	NOTIFICATION	03/11/1999	

—

MO/YR	CLS	TITLE	OR NO.	PO	CATEGORY	REPORT TYPE	DT 1	DT 2
03/01/1999	4	ON 2/9/99, ASBESTOS INSULATION WAS INADVERTENTLY REMOVED FROM CHILLED WATER LINE IN BUILDING 12-44 EQUIPMENT ROOM A	ALO-AO-MHSM-PANTEX-1999-0018	DP	OFF-NORMAL	NOTIFICATION	03/03/1999	
03/01/1999	4	ON 3/4/99 - BLASOCUT 2000 WATER SOLUBLE COOLANT LEAKAGE FROM SECONDARY CONTAINMENT INTO SOIL	CH-BH-BNL-BNL-1999-0008	SC	OFF-NORMAL	NOTIFICATION	03/08/1999	
03/01/1999	4	ON 2/22/99 AT BUSTED BUTTE - DIESEL FUEL RELEASE INTO SOIL - 10 CUBIC YARDS AFFECTED	HQ-SAYM-YMSGD-1999-0004	RW	OFF-NORMAL	UPDATE	03/02/1999	03/25/1999
03/01/1999	4	NPDES PERMIT NONCOMPLIANCE - WATER TREATMENT PLANT - MAXIMUM DAILY LIMIT EXCEEDED FOR SELENIUM - 3/1/99 - 55.6 MICROGRAMS/LITER VERSUS DAILY LIMIT OF 50 MICROGRAMS/LITER	ORO-MK-WSSRAP-1999-0010	EM	OFF-NORMAL	NOTIFICATION	03/18/1999	

—

MO/YR	CLS	TITLE	OR NO.	PO	CATEGORY	REPORT TYPE	DT 1	DT 2
03/01/1999	4	NOTICE OF VIOLATION OF NPDES PERMIT FOR PERIOD ENDING DECEMBER 31, 1998 - OUTFALL 201 - DECEMBER 7, 1998 CHLORINE AVERAGE DAILY READING OF 0.26 MG/LITER VERSUS 0.019 MG/LITER PERMITTED	ORO-LMES-Y12SITE-1999-0014	DP	OFF-NORMAL	NOTIFICATION	03/29/1999	
03/01/1999	4	ON 3/18/99, INADEQUATE DESIGN OF FIRE DETECTION SYSTEM WAS DISCOVERED - ONLY ONE FIRE DETECTOR INSTALLED WHEN TWO ARE REQUIRED TO ACTIVATE HALON SUPPRESSION SYSTEM	SR-WSRC-HBLINE-1999-0009	EM	OFF-NORMAL	NOTIFICATION	03/19/1999	
03/01/1999	4	ON 3/23/99, A DRUM OF ASBESTOS WAS DISCOVERED STORED BEYOND COLORADO STATE TEMPORARY STORAGE TIME LIMITS	RFO-KHLL-WSTMGTOPS-1999-0005	EM	OFF-NORMAL	NOTIFICATION	03/25/1999	
03/01/1999	4	ON 3/8/99, NONCOMPLIANCE DISCOVERED WITH APPROVED TECHNICAL SPECIFICATIONS FOR BLDG. 12-116 FIRE SUPPRESSION SYSTEM - DISCOVERY OF UNAPPROVED SPRINKLER HEADS	ALO-AO-MHSM-PANTEX-1999-0022	DP	UNUSUAL	NOTIFICATION	03/11/1999	

—



MO/YR	CLS	TITLE	OR NO.	PO	CATEGORY	REPORT TYPE	DT 1	DT 2
03/01/1999	4	ON 3/1/99, FAILURE TO PERFORM TIMELY 6 MONTH PERIODIC SURVEILLANCE DOP TEST OF PORTABLE VENTILATION HEPA FILTER	SR-WSRC-FTANK-1999-0007	EM	OFF-NORMAL	NOTIFICATION	03/02/1999	
03/01/1999	4	ON 2/26/99, DISCOVERY OF POTENTIAL UNREVIEWED SAFETY QUESTION (USQ) - MIXED THORIUM WASTE CONSTITUENTS MAY EXCEED RCRA LEVELS	OH-FN-FDF-FEMP-1999-0005	EM	OFF-NORMAL	NOTIFICATION	03/01/1999	
03/01/1999	4	ON 2/24/99, CAVERN 107 INCIDENT - 10 IN. PIPE SECTION SLIPS OUT OF HITCH DURING INSTALLATION - DAMAGES 2 IN. CONNECTION ON CRUDE OIL HEADER RISER - CAUSES 2 GALLON OIL SPILL	HQ-SPR-BM-1999-0004	FE	OFF-NORMAL	NOTIFICATION	03/24/1999	
<b>Total for Class</b>		14						

—